

Final Inspection Report

Product Description

| | |
|--------------------------|---|
| Order Number | A190102601215 |
| Client Name | |
| Inspection Date | Jan 24, 2019 |
| Factory Name | |
| Product Category | Textile & Raw Material |
| Product Name | 100% cotton plain dyed cellular leno lattice design blanket |
| Style/Model Number | PBB-27-344 |
| P/O Number | |
| Order Quantity | 1008(PCS) |
| Actual Shipment Quantity | 1008(PCS) |

| | |
|-------------------------|----------------------------------|
| Inspector(s) | Mr. Ye(79928) |
| Inspection Started at | 08:52:58 Jan 24, 2019GMT |
| Inspection Completed at | 14:54:38 Jan 24, 2019GMT |
| Sampling Standard | AQL Level I (ANSI/ASQ Z1.4-2008) |
| Sample Size (PCS) | 32 |

Summary

| | | | |
|---------------------|---|-----------------|-------------------|
| Client Requirements | <p>特别注重 :尺寸 重量 洗标, 以及包装信息。 是否对应。 同批产品是否色差 其他根据检验公司常规标准</p> | | |
| Remarks | <p>1. For the inspection, vendor provided packing list, didn't provide reference sample.</p> <p>2. During inspection, 1008PCS was packed into 63 cartons, 100 % of the actual shipment quantity was packed.</p> <p>3.Detailed shipping carton package info and retail package information: 1PC/Poly bag, 16PCS/Carton.</p> <p>4. For style PBB-27-344, QC inspected 32PCS and found 2PCS with defects. Detailed info as below:</p> <ul style="list-style-type: none"> -Untrimmed thread end-Minor-2PCS <p>5. On-site test as below:</p> <ul style="list-style-type: none"> -Carton drop test-1Carton-Pass -Barcode scan test-1PC-Pass -Product weight-1PC-884g -shading test-5PCS-Pass | | |
| Brief Findings | Defect Classification | Quantity | Percentage |
| | Total (PCS) | 2 | 6.25% |
| | Critical (PCS) | 0 | 0.00% |
| | Major (PCS) | 0 | 0.00% |
| | Minor (PCS) | 2 | 6.25% |

Photo of inspector anti-bribery confirmation

Click here to view large photo



Photo of inspector anti-bribery confirmation

Inspector: Mr(s). Ye (Work ID no. 79928)

Photo time:2019-01-24 10:43:08

Click here to view large photo



Data Safekeeping for Inspector Anti-Bribery Confirmation

Click here to view large photo



Data Storage for Inspector Anti-Bribery Confirmation

Photo of inspector's on-site working records

[Click here to view large photo](#)

Photo of inspector's on-site working records
 Inspector: Mr(s). Ye (Work ID no. 79928)
 Photo time:2019-01-24 12:20:23

[Click here to view large photo](#)



Data Safekeeping for Inspector's On-Site Working Records

[Click here to view large photo](#)



Data Storage for Inspector's On-Site Working Records

1. Factory Building

[Click here to view large photo](#)



Factory Gate

[Click here to view large photo](#)



Main Buildings

2. Bulk Products

[Click here to view large photo](#)



Packed bulk(1/3)

[Click here to view large photo](#)



Packed bulk(2/3)

[Click here to view large photo](#)



Packed bulk(3/3)

[Click here to view large photo](#)



Packing list

3. Sampling

[Click here to view large photo](#)



Sampling cartons

[Click here to view large photo](#)



Inspection samples

4. Packing

[Click here to view large photo](#)



Master carton

[Click here to view large photo](#)



Main mark

[Click here to view large photo](#)



Side mark

[Click here to view large photo](#)



Master carton

size-Length-65CM-Width-35CM-Height-56CM

[Click here to view large photo](#)



Gross weight-Weight-15.6KG

[Click here to view large photo](#)



Carton open-quantity packed in the carton-16PCS-packing status and order requested information were conformed

[Click here to view large photo](#)



Corrugated layer

[Click here to view large photo](#)



Detail of package(1/4)

[Click here to view large photo](#)



Detail of package(2/4)

[Click here to view large photo](#)



Detail of package(3/4)

[Click here to view large photo](#)



Detail of package(4/4)

5. Style

[Click here to view large photo](#)



Product view-front(1/3)

[Click here to view large photo](#)



Product view-front(2/3)

[Click here to view large photo](#)



Product view-front(3/3)

6. Accessories

[Click here to view large photo](#)



Barcode

[Click here to view large photo](#)



Washing label(1/3)

[Click here to view large photo](#)



Washing label(2/3)

[Click here to view large photo](#)



Washing label(3/3)

[Click here to view large photo](#)



Insert card(1/2)

[Click here to view large photo](#)



Insert card(2/2)

7. Workmanship

[Click here to view large photo](#)



Untrimmed thread end-Minor-2PCS

8. Measurement

[Click here to view large photo](#)



Product

size-Length-228CM-Width-152CM(1/2)

[Click here to view large photo](#)



Product

size-Length-228CM-Width-152CM(2/2)

9. Test

[Click here to view large photo](#)



Carton drop test-1Carton-Pass(1/2)

[Click here to view large photo](#)



Carton drop test-1Carton-Pass(2/2)

[Click here to view large photo](#)



Barcode scan test-1PC-Pass

[Click here to view large photo](#)



Product weight-1PC-884G

[Click here to view large photo](#)



Shading test-5PCS-Pass

End of Report