

Final Inspection Report

Product Description

Order Number	A190112404119
Client Name	
Inspection Date	Apr 12, 2019
Factory Name	
Product Category	Apparel & Accessories
Product Name	MENS JOGGING PANTS
Style/Model Number	FP03X10
P/O Number	
Order Quantity	17984(PCS)
Actual Shipment Quantity	17984(pcs)

Inspector(s)	Ms. Lin(78146)
Inspection Started at	10:07:35 Apr 12, 2019GMT
Inspection Completed at	19:50:20 Apr 12, 2019GMT
Sampling Standard	Client Requirement
Sample Size (PCS)	50

Summary

Client Requirements			
Remarks	<p>1. For the inspection, vendor provided packing list, didn't provide reference sample.</p> <p>2. During inspection, 17984pcs was packed into 817 cartons, 100 % of the actual shipment quantity was packed.</p> <p>3. Detailed shipping carton package info and retail package information: 1pc packed into 1 polybag, 1pc packed into 1 main polybag; 22pcs packed into 1 carton; bulk was assortment packing; conformed with requested order, please check packing list for detailed packing information.</p> <p>4. For style FP03X10, QC inspected 50PCS and found 2PCS with defects. Detailed info as below: -Untrimmed thread ends-Minor-2pcs</p> <p>5. On-site test as below: -Zipper test-2pcs-Pass -Smell test-4pcs-Pass -Color variation test - Red - 4pcs - grade 5(no shading)</p> <p>6. Below pending points were found during inspection, need client check and confirm: -The measurement of hip were out of tolerance</p>		
Brief Findings	Defect Classification	Quantity	Percentage
	Total (PCS)	2	4.00%
	Critical (PCS)	0	0.00%
	Major (PCS)	0	0.00%
	Minor (PCS)	2	4.00%

Photo of inspector anti-bribery confirmation

[Click here to view large photo](#)

Photo of inspector anti-bribery confirmation

Inspector: Mr(s). Lin (Work ID no. 78146)
 Photo time:2019-04-12 19:08:42 Location:

[Click here to view large photo](#)



Data Safekeeping for Inspector Anti-Bribery Confirmation

[Click here to view large photo](#)



Data Storage for Inspector Anti-Bribery Confirmation

Photo of inspector's on-site working records

[Click here to view large photo](#)



Photo of inspector's on-site working records

Inspector: Mr(s). Lin (Work ID no. 78146)

Photo time:2019-04-12 19:10:17

[Click here to view large photo](#)



Data Safekeeping for Inspector's On-Site Working Records

[Click here to view large photo](#)



Data Storage for Inspector's On-Site Working Records

1. Factory Building

[Click here to view large photo](#)



Gates

[Click here to view large photo](#)



Main Buildings

2. Bulk Products

[Click here to view large photo](#)



Packed bulk

[Click here to view large photo](#)

HAPPY PROMISE APPAREL COMPANY LIMITED
Address: No. 3 Building, Xiamen Cyber Park, Huang da North Road, Longgang Central City, Xiamen, Fujian, China
Tel No. : +86-755-88499996

PACKING LIST

To: _____
Address: _____
Shipped From: _____
Customer No./Order No.: _____
Invoice No.: _____

Item No.	Item Name	Unit	Quantity	Weight	Volume	Material	Color	Size	Remarks
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

Packing list-packing status, packing list and order requested information-were conformed

3. Sampling

[Click here to view large photo](#)



Sampling cartons

[Click here to view large photo](#)



Inspection samples

4. Packing

[Click here to view large photo](#)



Master carton

[Click here to view large photo](#)



Main mark

[Click here to view large photo](#)



Side mark

[Click here to view large photo](#)



Master carton

size-Length-56cm-Width-38cm-Height-28cm

[Click here to view large photo](#)



Gross weight-12.03kg

[Click here to view large photo](#)



Carton open

[Click here to view large photo](#)



Corrugated layer

[Click here to view large photo](#)



Solid color and solid size packed polybag(1/2)

[Click here to view large photo](#)



Solid color and solid size packed polybag(2/2)

[Click here to view large photo](#)



Unit packed front

[Click here to view large photo](#)



Unit packed back

[Click here to view large photo](#)



Unit polybag opening

[Click here to view video](#)



Folding way

5. Style

[Click here to view large photo](#)



Product view-front

[Click here to view large photo](#)



Product view-back

[Click here to view large photo](#)



Product view-inside(1/2)

[Click here to view large photo](#)



Product view-inside(2/2)

[Click here to view large photo](#)



Details(1/2)

[Click here to view large photo](#)



Details(2/2)

[Click here to view large photo](#)



Details

[Click here to view large photo](#)



Details

6. Accessories

[Click here to view large photo](#)



Main label and size label(1/4)

[Click here to view large photo](#)



Main label and size label(2/4)

[Click here to view large photo](#)



Main label and size label(3/4)

[Click here to view large photo](#)



Main label and size label(4/4)

[Click here to view large photo](#)



Hangtag front side

[Click here to view large photo](#)

Hangtag back side

[Click here to view large photo](#)



Care label

7. Workmanship

[Click here to view large photo](#)



Untrimmed thread ends-Minor-2pcs(1/2)

[Click here to view large photo](#)



Untrimmed thread ends-Minor-2pcs(2/2)

9. Test

[Click here to view video](#)



Color variation test-Red-4pcs-grade 5(no shading)

[Click here to view video](#)



Zipper test-Quantity-2pcs-Pass

[Click here to view video](#)



Smell test-4pcs-Pass

End of Report